

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

## June 2025 - 27.384375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>			
<b>Inspection completed:</b>			
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

### Specified System

**Inspected**

Signs for Systems 1-13

Final Exit (means of escape to final exit)

Signs for Communicating Information for Evacuation (means of escape to final exit)

Smoke Separation (means of escape to final exit)

## May 2025 - 123.110625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/05/2025		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

### Specified System

**Inspected**

Signs for Systems 1-13

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

Smoke Separation (means of escape to final exit)

✓

## April 2025 - 218.836875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/04/2025		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

# Monthly Owners Inspection History

## BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland

Log book has been completed by the above inspector during monthly and annual visits

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

### March 2025 - 65.484375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/03/2025		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

<b>Contractor sign log book</b>	<b>Checked</b>
Log book is still at the location shown above	
Log book has been completed by All IQP Contractors	
Log book has been completed by the above inspector during monthly and annual visits	

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

### February 2025 - 161.210625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	25/02/2025		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

<b>Contractor sign log book</b>	<b>Checked</b>
Log book is still at the location shown above	
Log book has been completed by All IQP Contractors	
Log book has been completed by the above inspector during monthly and annual visits	

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

## January 2025 - 256.936875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/01/2025		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

### Specified System

**Inspected**

Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## December 2024 - 123.110625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/12/2024		
<b>Inspection completed:</b>	No		
<b>Not completed reason:</b>	premises closed for holiday period from the 19th		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

### Specified System

**Inspected**

Signs for Systems 1-13	
Final Exit (means of escape to final exit)	
Signs for Communicating Information for Evacuation (means of escape to final exit)	
Smoke Separation (means of escape to final exit)	

## November 2024 - 223.599375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	28/11/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

### Contractor sign log book

**Checked**

Log book is still at the location shown above

✓

# Monthly Owners Inspection History

## BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland

Log book has been completed by All IQP Contractors ✓  
Log book has been completed by the above inspector during monthly and annual visits ✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

### October 2024 - 70.246875

**Inspector:** Active Fire Consultants **Email:** joe@activefire.co.nz  
**Mobile:** 022 478 4777 **Phone:** 09 478 4777  
**Inspection date:** 31/10/2024  
**Inspection completed:** Yes  
**WOF location:** Main entry **Log book location:** site contact health and safety -claire  
**Email sent to:** **Email sent date:**

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

### September 2024 - 165.973125

**Inspector:** Active Fire Consultants **Email:** joe@activefire.co.nz  
**Mobile:** 022 478 4777 **Phone:** 09 478 4777  
**Inspection date:** 30/09/2024  
**Inspection completed:** Yes  
**WOF location:** Main entry **Log book location:** site contact health and safety -claire  
**Email sent to:** **Email sent date:**

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

## August 2024 - 261.699375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/08/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

<b>Contractor sign log book</b>	<b>Checked</b>
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

<b>Specified System</b>	<b>Inspected</b>
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## July 2024 - 123.110625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/07/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

<b>Contractor sign log book</b>	<b>Checked</b>
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

<b>Specified System</b>	<b>Inspected</b>
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## June 2024 - 218.836875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	25/06/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

<b>Contractor sign log book</b>	<b>Checked</b>
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

Log book has been completed by the above inspector during monthly and annual visits

✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## May 2024 - 65.484375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/05/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## April 2024 - 161.210625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/04/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

## March 2024 - 256.936875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	05/03/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## February 2024 - 123.110625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	02/02/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## January 2024 - 218.836875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/01/2024		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

Log book has been completed by the above inspector during monthly and annual visits



Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## December 2023 - 65.484375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	21/12/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## November 2023 - 161.210625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/11/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓



# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

## October 2023 - 256.936875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	30/10/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## September 2023 - 123.110625

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	21/09/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## August 2023 - 218.836875

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/08/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗

# Monthly Owners Inspection History

**BID: 3431 - Alto Packaging (#1), 1 Unity Drive, Rosedale, Auckland**

Log book has been completed by the above inspector during monthly and annual visits



Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓

## July 2023 - 65.484375

<b>Inspector:</b>	Active Fire Consultants	<b>Email:</b>	joe@activefire.co.nz
<b>Mobile:</b>	022 478 4777	<b>Phone:</b>	09 478 4777
<b>Inspection date:</b>	31/07/2023		
<b>Inspection completed:</b>	Yes		
<b>WOF location:</b>	Main entry	<b>Log book location:</b>	site contact health and safety -claire
<b>Email sent to:</b>		<b>Email sent date:</b>	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Systems 1-13	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
Smoke Separation (means of escape to final exit)	✓