

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

August 2025 - 27.384375

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:			
Inspection completed:			
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

Final Exit (means of escape to final exit)

Signs for Communicating Information for Evacuation (means of escape to final exit)

July 2025 - 118.348125

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	15/07/2025		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:	cdodds@argosy.co.nz	Email sent date:	2025-07-15

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Inspector comments:

Light between garden center and shop not sure weather there should be a exit sign or not .require fire report to determine.

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland



Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

June 2025 - 117.284375

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 27/06/2025

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

May 2025 - 208.248125

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 27/05/2025

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Specified System

	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

April 2025 - 51.196875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	03/04/2025		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book

Checked

Log book is still at the location shown above
Log book has been completed by All IQP Contractors
Log book has been completed by the above inspector during monthly and annual visits

Specified System

	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

March 2025 - 142.160625

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	10/03/2025		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book

Checked

Log book is still at the location shown above
Log book has been completed by All IQP Contractors
Log book has been completed by the above inspector during monthly and annual visits

Specified System

	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

February 2025 - 233.124375

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	17/02/2025		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

January 2025 - 75.009375

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 23/01/2025

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

December 2024 - 165.973125

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 23/12/2024

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Contractor sign log book

Checked

Log book is still at the location shown above

Log book has been completed by All IQP Contractors

Log book has been completed by the above inspector during monthly and annual visits

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

November 2024 - 256.936875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	18/11/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:	cdodds@argosy.co.nz	Email sent date:	

Contractor sign log book

Log book is still at the location shown above	Checked
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System

Signs for Specified Systems	Inspected
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

October 2024 - 118.348125

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	24/10/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book

Log book is still at the location shown above	Checked
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System

Signs for Specified Systems	Inspected
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

September 2024 - 209.311875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	13/09/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book

Log book is still at the location shown above	Checked
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

August 2024 - 51.196875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	30/08/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

July 2024 - 142.160625

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	30/07/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

June 2024 - 233.124375

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	17/06/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:	cdodds@argosy.co.nz	Email sent date:	2024-06-17

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓

Inspector comments:
Exit door in the warehouse area . Far right side of the storage area is jamming. Not opening.



Signs for Communicating Information for Evacuation (means of escape to final exit)	✓
--	---

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

May 2024 - 252.046875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	29/05/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓
Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

April 2024 - 118.348125

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	18/04/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓
Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

March 2024 - 209.311875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	04/03/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

February 2024 - 51.196875

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	16/02/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

January 2024 - 142.160625

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	11/01/2024		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Contractor sign log book	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✓
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓

December 2023 - 233.124375

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	04/12/2023		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:		Email sent date:	

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

Contractor sign log book

Checked

Log book is still at the location shown above

✓

Log book has been completed by All IQP Contractors

✓

Log book has been completed by the above inspector during monthly and annual visits

✓

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

November 2023 - 75.009375

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 28/11/2023

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Contractor sign log book

Checked

Log book is still at the location shown above

✓

Log book has been completed by All IQP Contractors

✓

Log book has been completed by the above inspector during monthly and annual visits

✓

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

October 2023 - 165.973125

Inspector: Pulse Fire | Vinay/Anish

Email: pulsefireltd@gmail.com

Mobile: 021 123 5828

Phone: 0800 478 753

Inspection date: 20/10/2023

Inspection completed: Yes

WOF location: Behind Customer Service Desk

Log book location: By the Security desk at the main entry /exit in a wall box.

Email sent to:

Email sent date:

Log book comments: Not signed in SS1 , SS2 , SS4 , SS7 , SS9

Contractor sign log book

Checked

Log book is still at the location shown above

✓

Log book has been completed by All IQP Contractors

✗

Log book has been completed by the above inspector during monthly and annual visits

✓

Specified System

Inspected

Signs for Specified Systems

✓

Final Exit (means of escape to final exit)

✓

Signs for Communicating Information for Evacuation (means of escape to final exit)

✓

Monthly Owners Inspection History

BID: 4095 - The Warehouse, 11 Coliseum Drive, Albany, Auckland

September 2023 - 261.699375

Inspector:	Pulse Fire Vinay/Anish	Email:	pulsefireltd@gmail.com
Mobile:	021 123 5828	Phone:	0800 478 753
Inspection date:	14/09/2023		
Inspection completed:	Yes		
WOF location:	Behind Customer Service Desk	Log book location:	By the Security desk at the main entry /exit in a wall box.
Email sent to:	cdodds@argosy.co.nz	Email sent date:	2023-09-14
Log book comments:	Not signed in SS1 , SS2 , SS4 , SS7 , SS9		

Contractor sign log book

	Checked
Log book is still at the location shown above	✓
Log book has been completed by All IQP Contractors	✗
Log book has been completed by the above inspector during monthly and annual visits	✓

Specified System

	Inspected
Signs for Specified Systems	✓
Final Exit (means of escape to final exit)	✓
Signs for Communicating Information for Evacuation (means of escape to final exit)	✓